

# Installation Instructions

## VERTICAL RING CABLE MANAGER, 600W TERAFRAME

### Intended Use

Vertical Cable Ring Managers attach to the side of the equipment mounting rails and feature plastic C-shaped cable management rings to guide and manage network cables, signal cables and patch and equipment cords.

### Tools Required


10 mm open-end, box or socket wrench

### Included Hardware

- (2) Vertical ring cable managers
- (4) M6X12 screws
- (4) M6 Serrated flange nuts.

### Assembly Sequence

1. Two cable managers are supplied in each kit.
2. Position flat flange of the cable manager against the flat outer surface of the rail as shown.
3. Position cable manager with mount hole closest to adjustable top and bottom slides.
4. Install screws and nuts through the cable manager and through the rail.



**CHATSWORTH PRODUCTS, INC.**

IIS-716275-001, 03/05/10, Rev. 1, CPI/J Davis

800-834-4969 (USA & Canada) • [www.chatsworth.com](http://www.chatsworth.com) • [techsupport@chatsworth.com](mailto:techsupport@chatsworth.com)

For international phone numbers, see our website or contact CPI Tech Support.

*This drawing contains proprietary and confidential information and is protected by U.S. and international law. Unauthorized reproduction, disclosure or use of the drawing or the information therein is expressly forbidden except as agreed to in writing by Chatsworth Products, Inc.*