



	REVISION			
	DESCRIPTION	DATE	APPROV CHK	'ED ENG
DM_EC	CO_C-11870	SJG 01/16/2023	SJG 01/16/2023 0	SJG
wn w Wan Enter Ckwis S.	DE THE CABINET WILL HI ITH THE HINGE ON THE L T THE HINGE ON THE RIC CHASSIS BY ROTATING E AND SWING IT OPEN T	NGE FRO .EFT SIDE, SHT SIDE. THE BLUE TO GET A	M. THE INVERT TH LATCH CCESS TC	ΗE
IS SITT HINGE	ING ON A TABLE, LOOSI ES AND REMOVE THE HIM	IGE PINS	=i FROM	
FRAM	E APART FROM THE CEN	NTER CHA	ASSIS.	
	REMOVE HI BOTH HING		CHASSIS	4PART
DATE 05/2018	CPI CHATSWOR	TH PROI	DUCTS, IN	C.
05/2018				
	INSTL INSTR,CUBE-IT,G3			
)5/2018				
		4090		iss 5
	SCALE 1:4 SHEET	1	OF 5	-



IIS-740900, SHEET 3 OF 5 - INSTL INSTR, CUBE-IT, G3 - 1:4 - 01/16/2023 - ISS. 5 - CPI/S. GIBBLE



MOUNTING CABINET TO REAR FRAME

WARNING: FAILURE TO TIGHTEN HINGE SET SCREWS MAY **RESULT IN EQUIPMENT DAMAGE, PERSONAL INJURY, OR DEATH**

